



Enstrom Maintenance Alert

08/03/2015

Part number: 28-11307-1

Part description: MOUNT CABIN SEAT LT

Enstrom: 280C; S/N 1069, Time in Service 1190



It was reported that a technician found a cracked pilot's side cabin cyclic bell crank mount (P/N 28-11307-1) on a 280C helicopter. Enstrom recommends inspecting both co-pilots, and pilot's side mounts carefully during scheduled inspections or any time the seat deck is removed.