



# SERVICE INFORMATION LETTER

---

---

SERVICE INFORMATION LETTER NO. T-003  
Page 1 of 2

- DATE: June 21, 1996
1. SUBJECT: Engine Oil Warning Placard
2. MODELS: TH-28 and 480 Helicopters
3. EFFECTIVITY: All Serial Numbers
4. BACKGROUND:

The Allison Engine Company warns about the mixing of different type and brand engine oils in the Allison 250 Series Operation and Maintenance Manual. Enstrom also warns about the mixing of different engine oils in the TH-28 and 480 Rotorcraft Flight Manuals and in the TH-28/480 Maintenance Manual. Enstrom has released a warning placard (Figure 1) to be installed on the inside surface of the right side engine access panel to help reduce the possibility of inadvertant engine oil mixing.

5. COMPLIANCE:

At or before the next 100 hour inspection, install the Engine Oil Warning Placard, P/N 4119892-11, on the right side engine access panel at the location shown in Figure 2.

5.1. PARTS

| <u>Nomenclature</u>         | <u>Part Number</u> | <u>Quantity</u> |
|-----------------------------|--------------------|-----------------|
| Placard, Engine Oil Warning | 4119892-11         | 1 Ea.           |

6. MAN HOURS: .1 Hours
7. WARRANTY: Not applicable
8. WEIGHT CHANGES: None
9. LOG BOOK ENTRY: Enter compliance with this Service Information Letter.
10. REPETITIVE INSPECTIONS: None




Figure 1.




Figure 2.