



# Enstrom Maintenance Alert

**12/17/14**

**28-16186-1 Pilot Collective Socket**

**Enstrom: F-28C; S/N 429, Time in Service Unknown**



It was reported that a technician found a cracked pilot's collective socket (P/N 28-16186-1) on a F28-C helicopter. The time and history of the helicopter is not known. Enstrom recommends inspecting the collective mounts carefully during scheduled inspections or any time the collective cover is removed.

SDB's 0050, & 105 also apply to issues that have occurred with the collective system.