

September 5, 2018

TO: Recipients of Enstrom Helicopter Service Information Letters

SUBJECT: CANCELLATION OF SERVICE INFORMATION LETTER NO. 0050,

LIMIT RANGE ON ROTOR TACHOMETER

This letter transmits the cancellation of Service Information Letter (SIL) No. 0050.

Updated rotor tachometers that show the correct rotor RPM minimum limit of 332 RPM have been supplied to owners of all affected Enstrom "C" Model aircraft.

TECHNICAL PUBLICATIONS
ENSTROM HELICOPTER CORPORATION