



**THE ENSTROM HELICOPTER CORPORATION**  
**TWIN COUNTY AIRPORT, P.O. BOX 490, MENOMINEE, MICHIGAN 49858**

# SERVICE INFORMATION LETTER

---

---

SERVICE LETTER NO. 0013

DATE: September 25, 1969

SUBJECT: Inlet Air Ducting

MODEL: F-28A

SERIAL NO: All

It has been found from in service reports that one instance of inlet air restriction has been encountered.

To prevent any further occurrences, it is recommended that the inlet ducting be inspected upon receipt of this letter. This visual inspection is to pay particular attention to the inner wire support, and or any evidence of buckling. If ducting is found, unsatisfactory replace with AER-Duct of the following grade only: SCEET - 2 ply Fiberglass Fabric, Silicone Rubber Impregnation (Color Red). This replacement may be acquired from any aircraft supply house or direct from the Enstrom Corporation.

All ducting to be changed to the approved type on or before the next 50 Hour inspection.