SERVICE INFORMATION LETTER

SERVICE LETTER NO. 0030

Date: October 10, 1972

Subject: Collective Control Assembly (Pilot Stick)

Model: F-28A

Serial No: All

Two instances have been reported in which the AN509-8R5 screws in the pilot's collective control grip have loosened up. To prevent any further occurrences, it is recommended that all helicopters be checked and the screws secured with type "A" Loc-Tite at your earliest convenience.

Within a few weeks you will receive two replacement Nylock screws which should be substituted for those presently installed.

