



February 16, 2000

TO: Recipients of Enstrom Helicopter Service Directive Bulletins.

SUBJECT: CANCELLATION OF SERVICE DIRECTIVE BULLETIN NO. T-001,  
POSSIBLE INGESTION OF INLET DUCT BOOTS.

This letter transmits the cancellation of Service Directive Bulletin No. T-001. The appropriate information in the bulletin has been incorporated into the TH-28/480 Maintenance Manual.

TECHNICAL PUBLICATIONS  
ENSTROM HELICOPTER CORPORATION