



SERVICE INFORMATION LETTER

SIL T-071
Page 1 of 2

- DATE: August 14, 2019
1. SUBJECT: Lamiflex Bearing Discontinuation
 2. MODEL: 480
 3. EFFECTIVITY: All
 4. BACKGROUND:

This Service Information Letter (SIL) is to make aircraft owners/operators aware that Enstrom is discontinuing the Lamiflex main rotor thrust bearings (P/N 28-14320-15). Enstrom has a limited supply of the bearings and once current supplies are exhausted, they will no longer be available. The Lamiflex bearings are being replaced with a tension-torsion (T-T) strap configuration.

5. COMPLIANCE:

When Lamiflex bearings are no longer available, owners/operators will need to convert their aircraft to a T-T strap configuration. These conversions are available as an STC from Airwolf Aerospace or from Enstrom Product Support as referenced in Table 1.

Table 1: Vendor Information

Part Number*	Manufacturer*	
AA-ECD-084-480 (STC SR03465CH)	Airwolf Aerospace LLC 15369 Madison Road Middlefield, OH 44062-8404	(440) 632-1687 (440) 632-1685 Fax www.airwolfaerospace.com info@airwolfaerospace.com
Contact Enstrom Product Support	Enstrom Helicopter Corporation 2209 22 nd Street Menominee, MI 49858	(906) 863-1200 (906) 863-6821 Fax www.enstromhelicopter.com customerservice@enstromhelicopter.com

August 14, 2019

6. SPECIAL TOOLS: N/A
7. MAN-HOURS: N/A
8. WARRANTY: Per Enstrom Helicopter Warranty policy
9. WEIGHT CHANGE: N/A
10. LOG BOOK ENTRY: N/A
11. REPETITIVE INSPECTIONS: N/A