

SDB #	DATE	REV. DATE	TITLE	EFFECTIVITY			STATUS			
				TH-28	480	480B	ONE TIME	RECURRING	FAA AD	CANCELED
T-001	CXL		POSSIBLE INGESTION OF INLET DUCT BOOTS	X	X					X
T-002 Rev. A	09/11/95	12/04/96	MRGB, P/N 4130020, CRACKED RING GEAR CARRIER	X	X			X		
T-003	06/06/96		POSSIBLE INTERFERENCE INVOLVING MAIN ROTOR PITCH CHANGE BELL CRANK (Cyclic Walking Beam)	X	X			X		
T-004	06/11/96		INCORRECT LENGTH HORIZONTAL STABILIZER CAP SCREW	X	X			X		
T-005 Rev. B	CXL		REPLACEMENT OF LOWER PULLEY BEARINGS, P/N ECD-4018	X	X		X			X
T-006	02/13/97		CRACKED ISOLATION MOUNT WELDMENT	X	X		X			
T-007	05/28/97		CRACKS IN LOWER SWASHPLATE UNIVERSAL HOUSING, P/N 4140535-11	X	X			X		
T-008R3	05/28/97	05/27/16	CRACKED OIL COOLER BLOWER SHORT SHAFT	X	X	X	X			
T-009	10/03/97		IMPROVED FUEL SHUTOFF VALVE OPERATION	X	X		X			
T-010R1	CXL		SWASHPLATE INSPECTION	X	X					X
T-011	CXL		POSSIBLE INGESTION OF BELLMOUTH ENGINE INLET SEAL	X	X					X
T-012R1	10/16/98	01/07/14	TAIL ROTOR GEARBOX INPUT SEAL	X	X			X		
T-013R2	02/15/99	08/05/02	CRACKED OIL COOLER BLOWER SHAFT FLEX PLATES, P/N 28-01041	X	X	X		X		
T-014R1	03/22/00	10/06/00	LANYARD INSTALLATION FOR TAILCONE VIBRATION ABSORBER	X	X		X			
T-015	10/06/00		REPLACEMENT OF THE LOW POINT FUEL DRAIN VALVE	X	X		X			
T-016	02/15/02		OIL COOLER IMPELLER ASSEMBLY INSPECTION	X	X			X		
T-017	CXL		LOWER PULLEY DRIVE SYSTEM INSPECTION	X	X	X		X		X
T-018	06/16/03		H-STRUT INSPECTION	X	X	X		X		
T-019R2	09/10/03	04/02/19	MAIN ROTOR PUSH-PULL ROD INSPECTION	X	X	X	X		X ¹	
T-020	08/18/05		INSPECTION OF PYLON ASSEMBLY FOR CRACKS	X	X	X	X			
T-021	08/25/05		INSTALLATION OF OLEO CONDITION PLACARDS		X		X			
T-022	12/23/06		OVERRUNNING CLUTCH OIL LEVEL	X	X	X		X		
T-023	CXL		INCORRECT MARKING OF ECD002-11 BEARING SET	X	X	X	X			X
T-024	04/28/06		INSPECT SWASHPLATE ROD END (DOG LEG) ASSEMBLY, P/N 28-16143-1, FOR EXCESSIVE PLAY/WEAR	X	X	X		X		
T-025	05/23/06		INSPECT MAIN ROTOR CONTROL RODS, P/N 4140532-5, FOR LOOSE UPPER FITTINGS	X	X	X		X		
T-026R1	06/01/06	02/14/14	POWER OUTPUT SHAFT BEARING INSPECTION	X	X	X	X			
T-027R1	09/05/06	01/08/08	OVERRUNNING CLUTCH COVER EQUIPPED WITH A SIGHT PLUG	X	X	X		X		
T-028R2	02/26/07	05/24/16	TURBINE ENGINE ASSEMBLY – STEADY STATE OPERATION AVOIDANCE RANGE LIMIT	X	X	X	X			

SDB #	DATE	REV. DATE	TITLE	EFFECTIVITY			STATUS			
				TH-28	480	480B	ONE TIME	RECURRING	FAA AD	CANCELED
T-029	03/20/07		HINGE PINS (MAIN ROTOR BLADE RETENTION PINS), P/N 28-14007-3, MANUFACTURED FROM INCORRECT SPECIFICATION MATERIAL	X	X	X	X		X ²	
T-030	05/14/07		INSPECTION OF CIRCUIT BREAKER BUS BAR INSTALLATION			X	X			
T-031	10/18/07		INSPECTION OF HORIZONTAL STABILIZER SPAR THREAD ENGAGEMENT	X	X	X				
T-032	07/25/08		TAIL ROTOR CABLE CLEARANCE	X	X	X	X			
T-033R1	12/23/09		INSPECTION OF TAILCONE SKINS FLANGES, AND LONGERONS	X	X	X				
T-034	10/13/08		MAIN ROTOR PITCH CHANGE BELLCRANK	X	X	X	X			
T-035	11/03/08		MAIN ROTOR PITCH CHANGE BELLCRANK MISSING CHAMFERS	X	X	X	X			
T-036R1 ^a	01/28/09	12/12/23	DRIVE SYSTEM FLEX PACKS	X	X	X	X			
T-037	CXL		DRIVE BELT CLEARANCE	X	X	X	X			X ^b
T-038R1	02/26/10	05/05/11	ENGINE MOUNTS	X	X	X		X		
T-039R3	03/29/11	07/06/11	CYCLIC TRIM SYSTEM	X	X	X	X		X ³	
T-040	09/26/11		TRIM SWITCH ASSEMBLY INSPECTION	X	X	X	X			
T-041	11/28/11		MOUNTING HARDWARE INSPECTION	X	X	X	X			
T-042R2	6/28/12	11/07/17	CYCLIC CONTROL TUBE AND STOP RING ASSEMBLY INSPECTION	X	X	X	X			
T-043	01/09/13		TRIM RELAY REPLACEMENT	X	X	X	X			
T-044			[RESERVED]							
T-045R1	01/07/14	06/25/14	COPILOT COLLECTIVE – RETENTION PIN INSTALLATION		X	X	X			
T-046R3	07/07/14	11/07/17	MAIN ROTOR DRIVE BELT		X	X		X		
T-047	09/25/14		TAIL ROTOR DRIVE SHAFT BEARING ASSEMBLY	X	X	X	X			
T-048	09/18/14		ENGINE IDLE STOP ASSEMBLY			X	X			
T-049	11/06/14		OVERRUNNING CLUTCH ASSEMBLY		X	X	X			
T-050R3	02/11/15	06/24/16	MAIN ROTOR SPINDLE (LAMIFLEX), P/N 28-14282-13		X			X	X ⁴	
T-051	02/16/15		FUEL TANK INSPECTION	X	X	X	X			
T-052	11/16/15		ENGINE IDLE STOP WIRING			X	X			
T-053	11/02/16		PARTICLE SEPARATOR ASSEMBLY		X	X	X			
T-054	02/03/17		LAMIFLEX BEARING INSPECTION		X			X		
T-055R1	04/07/17	11/10/17	TAIL ROTOR ROTATING CONTROLS INSTALLATION INSPECTION	X	X	X		X		
T-056	05/19/17		SHOULDER HARNESS ATTACHMENT INSPECTION		X	X	X			
T-057	07/06/17		FUEL QUANTITY TRANSMITTER – COVER AND GASKET		X	X	X			
T-058R1	08/02/17	06/20/18	ROD END INSPECTION	X	X	X		X	X ⁵	
T-059	08/02/17		FUEL QUANTITY INDICATOR IDENTIFICATION		X	X	X			
T-060R1	05/24/18	09/05/18	FIBERGLASS PROCEDURE FOR UPPER PLENUM/ AIR INLET HAND HOLDS AND NUTPLATE RIVETS		X	X	X			

SDB #	DATE	REV. DATE	TITLE	EFFECTIVITY			STATUS			
				TH-28	480	480B	ONE TIME	RECURRING	FAA AD	CANCELED
T-061R1	9/25/19	10/29/19	LOWER AIR PLENUM WEDGE VANE		X	X	X			
T-062R2	8/27/19	06/05/20	DRAG STRUT ASSEMBLY INSTRUCTIONS		X	X		X		
T-063	9/10/19		CARGO HOOK EXTENSION LINK INSPECTION		X	X	X			
T-064	8/25/20		TAILCONE BULKHEAD INSPECTION		X	X		X		
T-065	10/13/20		TRANSMISSION MOUNT – PYLON JOINT CRACKS		X	X		X		

Notes

- ^a Includes Work Aid Document (WAD) T-001, Revision 1 or later.
- ^b Incorporated into the TH-28/480 Series Maintenance Manual (para. 13-29, B and 13-31, B).
- ^c Typo corrections only for August 2, 2018 issue (revision level/revision dates corrected for T-042, T-046, and T-055)

The following FAA Airworthiness Directives are related to the Service Directive Bulletin. Refer to the FAA Airworthiness Directive database for Airworthiness Directives not related to a Service Directive Bulletin.

- ¹ AD 2007-11-02
- ² AD 2007-16-01
- ³ AD 2012-11-05
- ⁴ AD 2018-02-01
- ⁵ AD 2017-26-03 (Update pending)