



THE ENSTROM HELICOPTER CORPORATION
TWIN COUNTY AIRPORT, P.O. BOX 490, MENOMINEE, MICHIGAN 49858

SERVICE INFORMATION LETTER

SERVICE INFORMATION LETTER NO. 0085

Date: December 19, 1978

Subject: Recommended Transmission Overhaul Interval

Model: F-28A 280 When Applicable
F-28C, 280C - All Serial Numbers

Effectivity: Not Applicable

The factory recommended tune between overhaul (TBO) is increased to 1200 hours for main rotor and tail rotor transmissions which meet the following requirements.

1. Main rotor transmissions that have documented proof that all Service Directive Bulletins and Airworthiness Directives have been complied with.
2. Main rotor transmission that have been manufactured or overhauled by a factory authorized service facility since September 1, 1975.
3. Tail rotor transmissions - Serial numbers 001-001-7411 and up, manufactured since June 1, 1974.

NOTE: These transmission may be readily identified by the dome shaped end of the gear box casting opposite the out-put shaft exit.