



Technical Tip:

Due to the unavailability of an approved Insight GEM replacement, it may be necessary to retrofit piston Enstroms with a JPI Engine Monitor.



To receive the correct installation parts you will need to order:

QTY	Part Number and description
1	EGT-701-4C-A-T Indicator w/software
1	700702-16 Harness
4	M-111 EGT Probe
3	M-5050 CHT Probe Kit
1	M111T TIT Probe w/Harness
1	MM-113-3/8 CHT Probe
1	400510 OAT Probe w/ Harness