

August 25, 2010

TO: Recipients of Enstrom Helicopter Service Directive Bulletins.

SUBJECT: CANCELLATION OF SERVICE DIRECTIVE BULLETIN NO. T-005 Rev. B,

REPLACEMENT OF LOWER PULLEY BEARINGS, P/N ECD-4018.

This letter transmits the cancellation of Service Directive Bulletin (SDB) No. T-005. P/N ECD-4018 bearings have been removed from all applicable aircraft.

TECHNICAL PUBLICATIONS
ENSTROM HELICOPTER CORPORATION