



February 16, 2000

TO: Recipients of Enstrom Helicopter Service Directive Bulletins.

SUBJECT: CANCELLATION OF SERVICE DIRECTIVE BULLETIN NO. T-010,
SWASHPLATE INSPECTION

This letter transmits the cancellation of Service Directive Bulletin No. T-010. The appropriate information in the bulletin has been incorporated into the TH-28/480 Maintenance Manual.

NOTE

Revision 4 of the TH-28/480 Illustrated Parts Catalog contains spare/repair parts information for the latest design of the lower swashplate assembly, P/N 4140520-5. Enstrom will only provide spare/repair parts support for this design (P/N 4140520-5) of the lower swashplate assembly.

TECHNICAL PUBLICATIONS
ENSTROM HELICOPTER CORPORATION