

August 25, 2010

TO: Recipients of Enstrom Helicopter Service Directive Bulletins.

SUBJECT: CANCELLATION OF SERVICE DIRECTIVE BULLETIN NO. T-017,

LOWER PULLEY DRIVE SYSTEM INSPECTION.

This letter transmits the cancellation of Service Directive Bulletin (SDB) No. T-017. The appropriate information in the bulletin has been incorporated into the TH-28/480 Series Maintenance Manual.

TECHNICAL PUBLICATIONS
ENSTROM HELICOPTER CORPORATION