

August 25, 2010

TO: Recipients of Enstrom Helicopter Service Directive Bulletins.

SUBJECT: CANCELLATION OF SERVICE DIRECTIVE BULLETIN NO. T-023,

INCORRECT MARKING OF ECD002-11 BEARING SET.

This letter transmits the cancellation of Service Directive Bulletin (SDB) No. T-023. P/N ECD002-11 bearings have been removed from all applicable aircraft.

TECHNICAL PUBLICATIONS ENSTROM HELICOPTER CORPORATION