

SERVICE INFORMATION LETTER

SIL T-068 Page 1 of 2

DATE: May 24, 2017

SUBJECT: EASA Registration of G1000H-Equipped Model 480B Helicopters

MODEL: 480B

EFFECTIVITY: S/N Equipped with Garmin G1000H Integrated Flight Deck System

The Enstrom Model 480B, when equipped with the G1000H Integrated Flight Deck System, is eligible for certification as an EASA registered helicopter; however, EASA has enacted some additional conditions which must be met. This Service Information Letter (SIL) provides the instructions for the modification and documentation of helicopters necessary for EASA registration.

MODIFICATION:

Helicopters conforming to EASA.IM.R.122 Type Certificate Data Sheet and equipped with the G1000H must be modified in accordance with paragraphs 1 through 3.

1. Enstrom 480B G1000H Rotorcraft Flight Manual Supplement 28-AC-072:

- 1.1. Enstrom 28-AC-072 must be carried in the helicopter at all times.
 - 1.1.1. The following placard shall be placed in the vicinity of the PFD/MFD: (Reference 28-AC-072, Paragraph 1.2.1.b)

THIS HELICOPTER IS APPROVED FOR OPERATIONS UNDER DAY VFR NON-ICING **CONDITIONS ONLY**

1.1.1.1. The above mentioned placard supersedes Paragraph 1-17, Line 1, bottom placard of Basic Rotorcraft Flight Manual 28-AC-023.

2. Enstrom TH-28/480 Series Maintenance Manual Supplement 8:

2.1. Page xiii, **INTRODUCTION** Section, **NOTE** is amended as follows:

NOTE

The G1000H System Installation may include the GMA 350H audio panel. For information regarding the GMA 350H audio panel, refer to either the GMA 350H electrical schematic (Diagram 1-4), TH-28/480 Series Maintenance Manual Supplement 5, or 28-AC-073 Rotorcraft Flight Manual Supplement for GMA 350H operation.

2.2. Paragraph 1.1.12, Table 2, is amended as follows:

COMPONENT	IDENTIFICATION	SOFTWARE VERSION
GMA 350H	Audio Panel	See 28-AC-073

2.3. Page 3-1, **Paragraph 3.1**, **NOTE** is amended as follows:

NOTE

For information regarding the GMA 350H audio panel, refer to either the GMA 350H electrical schematic (Diagram 1-4), the TH-28/480 Series Maintenance Manual Supplement 5, or 28-AC-073 Rotorcraft Flight Manual Supplement for GMA 350H operation.

3. GMA 350H Interface

3.1. If the helicopter is equipped with the GMA 350H Audio Panel, refer to SIL T-069 for additional instructions for modification.