



THE ENSTROM HELICOPTER CORPORATION
TWIN COUNTY AIRPORT, P.O. BOX 490, MENOMINEE, MICHIGAN 49858

SERVICE INFORMATION LETTER

SERVICE LETTER NO. 0036

Date: February 4, 1974
Subject: Oil Sump Quick Drain Hose Assemblies
Model: F-28A Helicopters; 280 Helicopters
Effectivity: As Noted

The Enstrom Helicopter Corporation has been made aware of instances relating to the loss of oil on fixed wing aircraft with quick drain valves installed on the oil sump drain.

If any helicopters have a quick drain hose assembly installed on the engine sump, the following procedures are suggested:

1. The quick drain assembly should be installed and safety wired per proper aircraft practices.
2. The hose part of the quick drain assembly to be removed from the ship and installed only when the mechanic is changing oil. This will preclude inadvertent activating of the quick drain assembly.