



SERVICE INFORMATION LETTER

SERVICE INFORMATION LETTER NO. T-025

Page 1 of 2

DATE: May 4, 2007

1. SUBJECT: Main Rotor Damper Oil Part Number
2. MODEL: TH-28, 480, and 480B
3. EFFECTIVITY: All serial numbers
4. BACKGROUND:

The manufacturer of the silicone oil used in the main rotor dampers has changed the part number of the oil from L-45 to SF96-20. This Service Information Letter (SIL) provides information for ordering and usage of the SF96-20 oil.

5. COMPLIANCE:

Use the new part number (para. 5.1) when ordering silicon oil for the main rotor dampers.

NOTE

The L-45 and SF96-20 silicone oils are interchangeable and mixing of the oils is permitted.

- 5.1. CONSUMABLE MATERIALS

| Description | New Part Number | Old Part Number |
|--------------|-----------------|-----------------|
| Silicone Oil | SF96-20 | L-45 |

NOTE

Enstrom will continue shipping L-45 silicon oil until the current supply is exhausted.

6. SPECIAL TOOLS: N/A
7. MAN-HOURS: N/A
8. WARRANTY: N/A

May 4, 2007

9. WEIGHT CHANGE: N/A
10. LOG BOOK ENTRY: N/A
11. REPETITIVE TREATMENT: N/A