



THE ENSTROM HELICOPTER CORPORATION

2209 22nd STREET, MENOMINEE, MICHIGAN 49858

SERVICE INFORMATION LETTER

SERVICE INFORMATION LETTER NO. T-048

Page 1 of 1

DATE: June 22, 2011

1. SUBJECT: Retraction Notice, Maintenance Manual Supplement 4, Revision 2

2. MODEL: 480 and 480B Helicopters

3. EFFECTIVITY: Aircraft Equipped with Chelton EFIS, P/N 4220500-()

4. BACKGROUND:

Enstrom has inadvertently mailed TH-28/480 Series Maintenance Manual Supplement 4, Chelton Flight Systems FlightLogic EFIS, Revision 2, dated May 5, 2011, before it completed the approval process. This revision incorporated an alternate Analog Interface Unit (AIU), P/N 42-013001-0001, which has not been fully substantiated for the EFIS installation.

Enstrom is currently drafting revision 3 to amend the data and provide additional EFIS installation updates and clarifications.

5. COMPLIANCE:

The P/N 42-013001-0001 AIU is not approved for installation in the Enstrom 480 Series helicopters. Operators should disregard any reference to the P/N 42-013001-0001 AIU.

6. PARTS: None

7. SPECIAL TOOLS: N/A

8. MAN-HOURS: N/A

9. WARRANTY: N/A

10. WEIGHT CHANGE: N/A

11. LOG BOOK ENTRY: N/A

12. REPETITIVE ACTION: N/A