



ENSTROM

HELICOPTER CORPORATION

2209 22nd Street, P.O. Box 490
Menominee, Michigan 49858 U.S.A.
Telephone 906-863-1200
Fax 906-863-6821

February 15, 2002

TO: Recipients of Enstrom Helicopter Service Information Letters.

SUBJECT: CANCELLATION OF SERVICE INFORMATION LETTER NO. T-004,
IMPROVED TAIL ROTOR FEATHERING AXIS BUMPER, P/N 28-15033-13

This letter transmits the cancellation of Service Information Letter No. T-004. The tail rotor bumper, P/N 28-15033-13, referenced in this SIL has been replaced with a new tail rotor bumper, P/N 28-15033-15, which is included in the TH-28/480 Series Illustrated Parts Catalog, dated November 16, 2001

TECHNICAL PUBLICATIONS
ENSTROM HELICOPTER CORPORATION