## SERVICE INFORMATION LETTER

SERVICE INFORMATION LETTER NO. 0149

Page 1 of 1

DATE:

May 3, 1999

1. SUBJECT:

Lamiflex Bearing, P/N 28-14320-15, Usage

2. MODEL:

F-28A and 280

3. EFFECTIVITY:

All serial numbers

BACKGROUND:

Enstrom stopped procuring Lamiflex Bearing P/N 28-14310-1 a number of years ago and recently stopped procuring Lamiflex Bearing P/N 28-14320-12. Lamiflex Bearing P/N 28-14320-15 is the only Lamiflex Bearing available for new replacement parts.

This Service Information Letter provides installation approval for F-28A and 280 model aircraft manufactured by The Enstrom Helicopter Corporation.

## 5. COMPLIANCE:

Lamiflex Bearing P/N 28-14320-15 is approved for installation on F-28A and 280 model aircraft as referenced in paragraphs 2 and 3 of this Service Information Letter.

## NOTE

Do not use Lamiflex Bearing P/N 28-14320-15 with Lamiflex Bearing P/N 28-14310-1 or Lamiflex Bearing P/N 28-14320-12.

## 5.1. PARTS

<u>Description</u>	Old Part Number	New Part Number	Quantity Per Aircraft
Lamiflex Bearing	28-14310-1	28-14320-15	3 Each
Lamiflex Bearing	28-14320-12	28-14320-15	3 Each