



February 16, 2000

TO: Recipients of Enstrom Helicopter Service Information Letters.

SUBJECT: CANCELLATION OF SERVICE INFORMATION LETTER NO. T-005, MAIN
AND TAIL ROTOR TRANSMISSION CHIP INDICATIONS ON NEW OR
RECENTLY OVERHAULED TRANSMISSIONS

This letter transmits the cancellation of Service Information Letter No. T-005. The appropriate information in the bulletin has been incorporated into the TH-28/480 Maintenance Manual.

NOTE

This letter does not cancel Service Information Letter No. 0144
which is applicable to Enstrom's piston model helicopters.

TECHNICAL PUBLICATIONS
ENSTROM HELICOPTER CORPORATION