

September 15, 2016

TO: Recipients of Enstrom Helicopter Service Information Letters

SUBJECT: CANCELLATION OF SERVICE INFORMATION LETTER NO. T-021,

ELASTOMERIC MAIN ROTOR DAMPER KIT

This letter transmits the cancellation of Service Information Letter (SIL) No. T-021.

Because all fielded and current production main rotor hubs are assembled with hydraulic main rotor dampers as the current approved configuration, the superseded elastomeric main rotor damper configuration and associated installation kit are not supported.

TECHNICAL PUBLICATIONS
ENSTROM HELICOPTER CORPORATION