## SERVICE INFORMATION LETTER

October 6, 2000

TO: Recipients of Enstrom Helicopter Service Information Letters.

SUBJECT: CANCELLATION OF SERVICE INFORMATION LETTER NO. 0010,

REPLACEMENT OF WASHERS ON 28-13236 ACTUATOR ARM

This letter transmits the cancellation of Service Information Letter No. 0010. Replacement Harper Washers were provided to all owners/operators when this Service Information Letter was originally issued and does not apply to later production F-28 Series aircraft. The Illustrated Parts Catalog for F-28/280 series aircraft has the current part numbers incorporated.

TECHNICAL PUBLICATIONS ENSTROM HELICOPTER CORPORATION