



SDB #	DATE	REV. DATE	TITLE	EFFECTIVITY							STATUS			
				F-28A	280	F-28C	280C	F-28F	280F	280FX	ONE TIME	RECURRING	FAA AD	CANCELED
0001	04/12/67		MAIN ROTOR TRANSMISSION	X								X		
0002	07/26/67		MAIN ROTOR TRANSMISSION	X							X			
0003	07/27/67		IGNITION SYSTEM	X							X			
0004	05/10/68		TAIL ROTOR BLADE LIFE – P/N 28-15100	X								X		
0005	08/04/69		BELT DRIVE SUPPORT STRUT	X								X		
0006	10/23/69		LOWER JACK STRUT BEARING O- RING	X							X			
0007	10/24/69		TORQUE, M/R TRANSMISSION PINION SHAFT NUT	X	X							X		
0008A	07/14/71	10/22/71	MAIN ROTOR CONTROL PITCH LINK	X							X			
0009A	09/23/71	05/30/73	IDLER YOKE ASSEMBLY – P/N 28-13292 REV. A	X							X			
0010	CXL		INSPECT STABILIZER ATTACH TUBE P/N 28-11222	X										X
0011	03/29/72		TAPER PINS ON TAIL ROTOR DRIVE SHAFT	X							X		(1)	
0012	05/18/72		TAIL ROTOR OUTPUT SHAFT SEAL HOUSING	X							X			
0013	CXL		INSPECTION OF IDLER TENSION STRAPS P/N 28-13236	X	X									X
0014	09/25/72		MAIN ROTOR HUB NUT	X	X							X		
0015	02/26/73	02/28/73	CYCLIC STICK TORQUE TUBE ASSEMBLIES With AMENDMENT 1	X							X			
0016C	09/27/73	09/25/74	LOW OIL LEVEL IN TAIL ROTOR GEARBOX	X								X		
0017C	01/09/74	01/03/83	REVISED TRANSMISSION OVERHAUL LIFE	X	X						X		(13)	
0018A	01/24/74	02/15/74	RECOMMENDED FLIGHT PROCEDURE FOR PARTIAL LOSS OF POWER	X								X	(2)	
0019	CXL		RAPID ROTOR CLUTCH ENGAGEMENT	X	X									X
0020B	10/01/74	04/02/82	MAIN ROTOR SPINDLE – P/N 28-14282 EO #8	X							X			
0021C	10/01/74	04/02/82	MAIN ROTOR SPINDLE – P/N 28-14282	X							X		(4)	
0022	10/16/74		BACKFIRE DAMAGE TO INLET AIR SYSTEM	X	X							X		
0023	10/18/74		BELT TIGHTENING SYSTEM	X	X							X		
0024	12/17/74		MAIN ROTOR BLADE INSPECTION	X	X						X			

SDB #	DATE	REV. DATE	TITLE	EFFECTIVITY							STATUS			
				F-28A	280	F-28C	280C	F-28F	280F	280FX	ONE TIME	RECURRING	FAA AD	CANCELED
0025A	02/18/75	07/31/75	MAIN ROTOR HUB RETENTION	X	X						X		(5)	
0026	07/21/75		COOLING AIR TURNING VANE – P/N 280-126001-9		X						X			
0027	12/09/75		OVER-RUNNING CLUTCH ASSEMBLY	X	X							X	(23)	
0028	12/09/75		FUEL TANK VENT MANIFOLD	X	X						X			
0029A	12/09/75	01/21/76	TAILCONE ATTACHMENT BOLTS	X	X						X		(6)	
0030	12/09/75		BELLCRANK – TAIL ROTOR CONTROL SYSTEM P/N 28-16338	X	X						X			
0031	CXL		MAIN ROTOR SHAFT (Superseded by Service Directive Bulletin No. 0036)	X	X								(3)	X
0032	01/19/76		RUBBER HOSE IN AIRSPEED INDICATOR PITOT LINE	X	X						X			
0033	01/21/76		TAIL ROTOR CONTROL PITCH LINK RETENTION	X	X						X			
0034	01/22/76		COPILOT'S TAIL ROTOR PEDAL CLEARANCE	X							X			
0035A	03/01/76	07/09/90	UPPER SWASHPLATE BEARING	X	X	X	X					X	(22)	
0036	08/02/76		MAIN ROTOR SHAFT	X	X						X			
0037A	03/16/76	01/17/77	TAIL ROTOR SPINDLE	X	X	X	X					X	(8)	
0038	CXL		INSPECTION OF STABILIZER ATTACH TUBE	X										X
0039	05/12/77		INSPECTION OF TAIL ROTOR DRIVE SHAFT AFTER TAIL ROTOR STRIKE	X	X	X	X					X		
0040	05/20/77		REPLACEMENT OF WIDE CHORD TAIL ROTOR PITCH LINK RETAINER ASSEMBLY			X	X				X		(7)	
0041	CXL		TAIL ROTOR CABLE CORROSION IN ENGINE COMPARTMENT AREA			X	X				X			X
0042	06/28/77		READJUSTED WIDE CHORD TAIL ROTOR COUNTER WEIGHT			X	X				X			
0043	07/11/77		SPECIAL INSPECTION – TAIL ROTOR CONTROL			X	X				X			
0044	08/08/77		REPLACEMENT & INSTALLATION OF TAIL ROTOR THRUST BEARINGS	X	X	X	X				X			
0045	11/02/77		INADVERTENT ENGINE STOPPAGE ON POWER REDUCTIONS AT HIGH DENSITY ALTITUDES			X	X				X		(9)	
0046	12/02/77		DUAL COLLECTIVE STICK REINSTALLATION			X	X				X			
0047	12/13/78		MAIN ROTOR TRANSMISSION IDENTIFICATION			X	X				X			

SDB #	DATE	REV. DATE	TITLE	EFFECTIVITY							STATUS			
				F-28A	280	F-28C	280C	F-28F	280F	280FX	ONE TIME	RECURRING	FAA AD	CANCELED
0048A	04/05/79	09/08/80	WIDE CHORD TAIL ROTOR BLADE GRIP			X	X				X		(10)	
0049	04/03/79		MAIN ROTOR TRANSMISSION MOUNT BOLTS			X	X				X			
0050	07/01/80		SPECIAL INSTRUCTIONS: COLLECTIVE CONTROL BELLCRANK – P/N 28-16189	X	X	X	X				X			
0051	08/07/80		MAIN ROTOR TRANSMISSION MOUNTING HARDWARE	X	X	X	X				X			
0052	03/17/81		REPAIR OF FIVE WIRE CONNECTOR			X	X	X	X		X			
0053	04/30/81		COMPLIANCE TO AVCO LYCOMING SERVICE BULLETIN No. 454 "REPLACEMENT OF OIL PUMP IMPELLERS"			X	X	X	X		X			
0054R1	CXL		WESTGATE LINKAGE ASSEMBLY Superseded by Service Directive Bulletin No. 0107					X	X	X		X		X
0055A	12/02/81	04/02/82	CLUTCH CONTROL SYSTEM RIGGING AND HEAT PROTECTION	X	X	X	X	X	X		X		(12)	
0056	12/02/81		REPLACEMENT OF PITCH LINK RETAINER AND SERVICE IMPROVEMENT OF THE PITCH CONTROL SYSTEM			X	X				X			
0057	01/11/82		PERIODIC INSPECTIONS OF LAMIFLEX BEARINGS AND SHIMS IN MAIN ROTOR BLADE RETENTION ASSEMBLY	X	X	X	X	X	X			X	(11)	
0058	07/27/82		REMOVAL OF THE INDUCTION PRESSURE RELIEF VALVE			X	X				X			
0059	06/18/82		INSTALLATION OF COVERS ON RIGHT SIDE ENGINE COMPARTMENT DOOR LOUVERS			X	X	X	X		X			
0060	7/28/82		COMPLIANCE TO AVCO LYCOMING SERVICE BULLETIN No. 461 & BENDIX SERVICE BULLETIN No. 617A			X	X	X	X			X		
0061	11/12/82		CLUTCH ENGAGEMENT OVERCENTER LOCK WARNING LIGHT INST'L	X	X	X	X	X	X		X		(12)	
0062R1	11/02/82	03/28/25	BELT TENSIONING AND IDLER SYSTEM MODIFICATIONS	X	X	X	X				X			
0063	10/05/82		POSSIBLE BENDIX IMPOULSE COUPLING DEFECT AND EMERGENCY A.D.			X	X				X			
0064	10/19/82		COLLECTIVE FRICTION USAGE	X	X	X	X	X	X		X			
0065B	08/19/83	07/09/90	TAIL ROTOR DRIVESHAFT SPLINE COUPLINGS P/N 28-13609	X	X	X	X	X	X			X	(17)	

SDB #	DATE	REV. DATE	TITLE	EFFECTIVITY							STATUS			
				F-28A	280	F-28C	280C	F-28F	280F	280FX	ONE TIME	RECURRING	FAA AD	CANCELED
0066	10/01/84		LATERAL TRIM ACTUATOR CHANGE KIT No. 28-01027	X	X	X	X	X	X		X			
0067	10/01/84		NARROW CHORD TAIL ROTOR FORGED GRIPS	X	X							X		
0068A	05/08/86	07/09/90	LIFE LIMIT – OVER-RUNNING CLUTCH P/N 28-13401-1	X	X	X	X				X		(23)	
0069A	05/08/86	07/09/90	ESTABLISHED TBO ON OVER- RUNNING CLUTCH – P/N 28-13401-2 & -3	X	X	X	X	X	X	X	X		(23)	
0070	05/08/86		CLUTCH ENGAGEMENT HANDLE GUARD	X	X	X	X	X	X	X	X			
0071	05/08/86		IMPROVED PROCEDURE FOR IDLE MIXTURE ADJUSTMENT					X	X	X		X		
0072	CXL		ROTOR HEAD HUB PLATES	X	X	X	X	X	X	X				X
0073	05/15/87		WASTEGATE POSITION FIXITY					X	X	X	X			
0074	CXL		CONTROL CABLE CORROSION IN ENGINE COMPARTMENT	X	X	X	X	X	X	X		X		X
0075	06/08/87		TAIL ROTOR CABLE BLADE STRIKES			X	X	X	X	X		X		
0076R1	12/15/87	06/03/16	CRACKED STABILIZER SPAR – P/N 28-11222-1	X		X		X				X	(14)	
0077C	02/12/88	06/05/20	CRACKED TAIL ROTOR SPINDLE P/N 28-150064-11			X	X	X	X	X		X	(20)	
0078	10/18/89		TAIL ROTOR GEARBOX INSPECTION	X	X	X	X	X	X	X		X	(15)	
0079	10/18/89		LANDING GEAR LEG CRACKS – P/N 28-17132-1	X	X	X	X	X	X	X		X		
0080	10/18/89		TAIL ROTOR DRIVE FLEX COUPLINGS MANDATORY UPGRADE TO (7) PLATE COUPLING	X	X	X	X	X	X	X		X	(16)	
0081R2	11/01/91	02/03/17	LAMIFLEX BEARING INSPECTION	X	X	X	X	X	X	X		X	(21)	
0082A	11/16/92	03/18/93	INADVERTENT TRIM MOTOR OPERATION ON 24 VOLT D.C. SYSTEMS			X	X	X	X	X		X	(19)	
0083	07/16/93		WRAPPED MAIN ROTOR SHAFTS P/N 28-13183	X	X	X	X	X	X	X	X		(18)	
0084R2	09/11/95	10/27/10	MUFFLER MODIFICATION AND INSPECTION					X	X	X		X		
0085	CXL		COMPLIANCE WITH TEXTRON LYCOMING SERVICE BULLETIN NUMBER 524 AND OWNER'S ADVISORY #OA524	X	X	X	X	X	X	X				X
0086	CXL		ELECTRICAL SYSTEM MAINTENANCE AND INSPECTION FOR PROPER OPERATION, 12 VOLT (Superseded by Service Directive Bulletin No. 0090)	X	X	X	X						(24)	X

SDB #	DATE	REV. DATE	TITLE	EFFECTIVITY							STATUS			
				F-28A	280	F-28C	280C	F-28F	280F	280FX	ONE TIME	RECURRING	FAA AD	CANCELED
0087	11/19/96		MANDATORY SERIALIZATION OF DRAG LINKS			X	X	X	X	X	X			
0088	5/28/97		CRACKS IN LOWER SWASHPLATE UNIVERSAL HOUSING, P/N 28-16119-1	X	X	X	X	X	X	X		X		
0089R1	10/16/98	01/07/14	TAIL ROTOR GEARBOX INPUT SEAL	X		X	X	X	X	X		X		
0090R3	10/26/98	06/05/24	12 VDC VOLTAGE CONTROL SYSTEM MODIFICATION (Includes AMOC Approval, dated 07/22/24)	X	X	X	X					X	(24)	
0091R2	11/17/99	02/18/25	LOWER SWASHPLATE INSPECTION	X	X	X	X	a	a	a		X		
0092R3	03/06/00	08/03/15	FUEL QUANTITY SYSTEM CALIBRATION	X	X	X	X	X	X	X		X		
0093R1	03/06/00	12/09/03	TAIL ROTOR CONTROL CABLE INSPECTION	X	X	X	X	X	X	X	X			
0094R2	03/23/01	02/15/02	MAIN ROTOR SHAFT INSPECTION	X	X	X	X	X	X	X		X	(25)	
0095R1	08/05/02	10/15/12	IDLER PULLEY ACTUATOR ARM INSPECTION	X	X	X	X	X	X	X		X		
0096R2	09/10/03	04/02/19	MAIN ROTOR PUSH-PULL ROD INSPECTION	X	X	X	X	X	X	X	X		(26)	
0097	02/03/05		INCORRECT HARDWARE INSTALLATION ON SEAT BELT BRACKET, P/N 28-11467-1					X	X	X	X			
0098	CXL		INCORRECT MARKING OF ECD002-11 BEARING SET			X	X	X	X	X	X			X
0099	03/29/06		NON-CONFORMING TIE ROD ASSEMBLIES, P/N 28-16498-9 & 28-16498-101					X	X	X	X			
0100R1	04/28/06	09/30/2025	INSPECT SWASHPLATE ROD END (DOG LEG) ASSEMBLY, P/N 28-16143-1, FOR EXCESSIVE PLAY/WEAR	X	X	X	X	c	c	c		X		
0101	05/23/06		INSPECT MAIN ROTOR CONTROL RODS, P/N 28-16253-103/105, FOR LOOSE UPPER FITTINGS	X	X	X	X	X	X	X		X		
0102	03/20/07		HINGE PINS (MAIN ROTOR RETENTION PINS), 28-14007-3, MANUFACTURED FROM INCORRECT SPECIFICATION MATERIAL	X	X	X	X	X	X	X	X		(27)	
0103	05/03/07		INSPECTION OF TURBOCHARGER BYPASS TUBE			X	X				X			
0104	10/06/08		MAIN ROTOR PITCH CHANGE BELLCRANK	X	X	X	X	X	X	X	X			
0105	10/17/08		COLLECTIVE BELLCRANK INSPECTION	X	X	X	X	X	X	X		X		



September 30, 2025

Page 6 of 7

[illegible]

SDB #	DATE	REV. DATE	TITLE	EFFECTIVITY						STATUS				
				F-28A	280	F-28C	280C	F-28F	280F	280FX	ONE TIME	RECURRING	FAA AD	CANCELED
0131R1	01/16/20	01/17/20	TAIL ROTOR CONTROL CABLE CORROSION	X	X	X	X	X	X	X		X		
0132R1	12/9/21	11/21/23	CLUTCH HANDLE RIGGING	X	X	X	X	X	X	X		X		

* The following FAA Airworthiness Directives are related to the Service Directive Bulletin. Refer to the FAA Airworthiness Directive database for Airworthiness Directives not related to a Service Directive Bulletin.

(1) 72-11-04	(10) 79-10-06	(19) 93-24-13	(28) 2012-11-05
(2) 74-12-01	(11) 82-16-09	(20) 94-13-03	(29) 2018-02-01
(3) 74-17-07	(12) 82-24-01	(21) 94-17-15	(30) 2017-26-03
(4) 75-22-01	(13) 83-04-04	(22) 96-06-02	
(5) 75-22-10	(14) 88-11-06	(23) 96-06-03	
(6) 76-05-11	(15) 90-01-06	(24) 97-20-04	
(7) 77-15-04	(16) 90-17-02	(25) 2002-08-03	
(8) 77-20-02	(17) 90-17-03	(26) 2007-11-02	
(9) 77-25-05	(18) 93-15-10	(27) 2007-16-01	

Notes:

^a F-28F, 280F, and 280FX: Content incorporated into the F-28F/280F Series Maintenance Manual (Section 4 and Section 12).

^b F-28F, 280F, and 280FX: Content incorporated into the F-28F/280F Series Maintenance Manual (Section 10).

^c F-28F, 280F, and 280FX: Content incorporated into the F-28F/280F Series Maintenance Manual (Section 4 and Section 12).