



THE ENSTROM HELICOPTER CORPORATION
TWIN COUNTY AIRPORT, P.O. BOX 490, MENOMINEE, MICHIGAN 49858

SERVICE INFORMATION LETTER

October 6, 2000

TO: Recipients of Enstrom Helicopter Service Information Letters.

SUBJECT: CANCELLATION OF SERVICE INFORMATION LETTER NO. 0003, TAPER
PINS - TAIL ROTOR DRIVE SHAFT

This letter transmits the cancellation of Service Information Letter No. 0003. Replacement taper pins were provided to all owners/operators when this Service Information Letter was originally issued and does not apply to later production F-28 Series aircraft. The Illustrated Parts Catalog for F-28/280 series aircraft has the current part numbers incorporated.

TECHNICAL PUBLICATIONS
ENSTROM HELICOPTER CORPORATION