



THE ENSTROM HELICOPTER CORPORATION
TWIN COUNTY AIRPORT, P.O. BOX 490, MENOMINEE, MICHIGAN 49858

SERVICE INFORMATION LETTER

October 6, 2000

TO: Recipients of Enstrom Helicopter Service Information Letters.

SUBJECT: CANCELLATION OF SERVICE INFORMATION LETTER NO. 0028, BELT
ENGAGEMENT OVER-CENTERING CAPSULE ADJUSTMENT

This letter transmits the cancellation of Service Information Letter No. 0028. Replacement bushing adapters were provided to all owners/operators when this Service Information Letter was originally issued and does not apply to later production F-28 Series aircraft. The Illustrated Parts Catalog for F-28/280 series aircraft has the current part numbers incorporated. The latest revision of Service Information Letter No. 0080, Clutch Control and Belt Tension Rigging Procedure, provides the maintenance procedures for rigging the spring capsule assembly.

TECHNICAL PUBLICATIONS
ENSTROM HELICOPTER CORPORATION